

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Portland City Hall  
1220 S.W. Fifth AVE.  
Portland  
Multnomah County  
Oregon

HABS No. OR-125

Dallas Swogger, photographer, summer 1981

- |           |   |
|-----------|---|
| OR-125-1  | Main (west) elevation   |
| OR-125-2  | Detail of entrance, main elevation  |
| OR-125-3  | Rear (east) and north elevations  |
| OR-125-4  | East (partial) and south elevations   |
| OR-125-5  | East elevation, showing entrance bay  |
| OR-125-6  | Upper entrance bay detail, east elevation                                   |
| OR-125-7  | Entrance detail of columns, east elevation                                  |
| OR-125-8  | Entrance bay detail showing columns and pediment, east elevation            |
| OR-125-9  | Entrance bay detail showing inner columns, east elevation                   |
| OR-125-10 | Interior, looking towards west entry, marble floors                         |
| OR-125-11 | Interior, main floor (2nd), marble  |
| OR-125-12 | Interior, vault, auditor's office   |
| OR-125-13 | Interior, brass door knobs of all doors of main floor, some on other floors |